

Blender 2.9

shortcuts

- SHIFT z: switch wireframe and object mode
- f: fill faces or edges between edges or vertex
- a: select all
- ALT+a: select nothing
- c: circle select
- b: box select
- SHIFT+b: zoom to box
- SHIFT+s: cursor move or selection move
- w: cycle between selection modes

• numpad emulation

- edit → preferences → input → emulate numpad
- enable 1,2,3 switch faces,edges,vertex: edit → preferences → keymap → search mode
 - select mode toggle: ALT+1
 - select mode toggle: ALT+2
 - select mode toggle: ALT+3

fix boolean operations

Sometimes boolean difference fails. Before try on each object:

- edit mode
- select all vertices A
- vertex (top menu) → Merge Vertices → by distance (this operation remove duplicate vertices)

hide / show

- select (multiple) object and SHIFT+H to hide others
- recall others with ALT+H

edit mode

TAB key

- activate Vertex select with 1, Edge select with 2 and Face select with 3

Create new object from selected vertex:

- duplicate with SHIFT+d
- ESC to exit from grab mode
- parent selected with “p”
- exit from edit mode with TAB and you will have two objects

CTRL+I: select touching vertex, edges, faces

Recalculate normals (to solve bevel problems): select all with “a” and hit “shift+n”

knife mode K:

- c for angle constrain
- z for cut all deeper edges

put vertex same X, Y or Z:

- position the 3d cursor at the Y location
- set the pivot point to the 3d cursor (. period key)
- then scale by zero on the Y axis (S Y 0)

blendercam

Vevor 3018pro [amazon](#)


```
cd /lab/blender
git clone https://github.com/vilemnovak/blendercam.git
```

edit blender_manifest.toml commenting shapely wheels


install system packages

```
yay -S opencamlib python-numba python-shapely
```


setup blender scripts alternate file path




save preferences restart blender and enable blendercam add-on




select CAM render engine in scene tab




CAM machine → add preset '3018pro' with 'iso' post processing




CAM operations → add one operation and select target object




CAM material size and position → put object into job area with position button




CAM cutter





CAM operation setup → strategy parallel and **skin**



header gcode to increase velocity [spindle motor Genmitsu GS-775M 775](#) to 7000 (it double velocity x2)

```
M03 S1000
G4 P0.5
M03 S2000
G4 P0.5
M03 S3500
```

```
M03 S1000;G4 P0.5;M03 S2000;G4 P0.5;M03 S3500
```

Hey! Apologies for Necro'ing this thread but I think I have the exact same board and machine as you, and was running into the exact same problem. I don't know if you wound up solving your problem, but the change that worked for me was two fold:

- twist the spindle wires together between the motor and the board, adding a shield if necessary (I eventually removed the shielding when I accidentally damaged it)
- solder a 0.1uF ceramic capacitor (make sure it is bidirectional!!!) between each terminal of the spindle motor to the spindle motor body itself. Ideally, you would also solder a third capacitor

between each motor terminal, but I did not do so and have not yet had the random dropouts I did before.

From:

<https://wiki.csgalileo.org/> - **Galileo Labs**

Permanent link:

<https://wiki.csgalileo.org/tips/blender?rev=1744692965>

Last update: **2025/04/15 06:56**

