Blender 2.9

shortcuts

- SHIFT z: switch wireframe and object mode
- f: fill faces or edges between edges or vertex
- a: select all
- ALT+a: select nothing
- c: circle select
- b: box select
- SHIFT+b: zoom to box
- SHIFT+s: cursor move or selection move
- w: cycle between selecion modes

numpad emulation

- edit \rightarrow preferences \rightarrow input \rightarrow emulate numpa
- enable 1,2,3 switch faces, edges, vertex: edit \rightarrow preferences \rightarrow keymap \rightarrow search mode
 - select mode toggle: ALT+1
 - select mode toggle: ALT+2
 - select mode toggle: ALT+3

fix boolean operations

Sometimes boolean difference fails. Before try on each object:

- edit mode
- select all vertices A
- vertex (top menu) \rightarrow Merge Vertices \rightarrow by distance (this operation remove duplicate vertices)

hide / show

- select (multiple) object and SHIFT+H to hide others
- recall others with ALT+H

edit mode

TAB key

• activate Vertex select with 1, Edge select with 2 and Face select with 3

Create new object from selected vertex:

- duplicate with SHIFT+d
- ESC to exit from grab mode
- parent selected with "p"
- exit from edit mode with TAB and you will have two objects

CTRL+I: select touching vertex, edges, faces

Recalculate normals (to solve bevel problems): select all with "a" and hit "shift+n"

knife mode K:

- c for angle constrain
- z for cut all deeper edges

put vertex same X, Y or Z:

- position the 3d cursor at the Y location
- set the pivot point to the 3d cursor (. period key)
- then scale by zero on the Y axis (S Y 0)

blendercam

Vevor 3018pro vevor manual

```
cd /lab/blender
git clone https://github.com/vilemnovak/blendercam.git
```

edit blender_manifest.toml commenting shapely wheels

install system packages

yay -S opencamlib python-numba python-shapely

setup blender scripts alternate file path

	Blender Prefer	ences 🧕	3
	▼ Data		
	Fonts	<i>N</i>	٦
	Textures	<i>и</i> 🖻	٦
Linhts	Scripts	/lab/biender/biendercam/scripts	1
	Sounds	<i>II</i>	Ξ
	Temporary Files		1
	▼ Render		
	Render Output	//	٦
	Render Cache		1
Navigation	 Applications 		
	Image Editor		٦
	Animation Player	Internal	

save preferences restart blender and enable blendercam add-on

Blender Preferences								
	Official	Community						
		Store			A,			
	• 🖬 Scene: CAN - gcode	generation tools					â	\$
	File Add Author: Vike	tvlender tvlender com/scripts/adı m Novak	toms/comi_init_py					
	Warring: 🔺	there is no warranty for the pr	reduced gcode by now					
	istarrat: 🔛	Document	bilian	•		Remove		
	Professional							
	🖩 Store experimental features							
							A	

select CAM render engine in scene tab

	ν Δ β Scene	5Î			
έ¥	Render Engine Cam	¥			
Ċ.	* CAM chains				
8					
45					
S					
\mathbb{R}	* CAM operations				
s					
		A			
	* CAM info & warnings	-			
ి					
	Add operation first				
	CAM Material size and position				
	Add operation first				

CAM machine \rightarrow add preset '3018pro' with 'iso' post processing



CAM operations \rightarrow add one operation and select target object

Last update: 2025/04/15 16:01

 CAM opera 	tions				
Operation_1			+		
			7		
•					
Operation pre	esets	~ +			
	Calculate path				
	Calculate path in background				
	Simulate this operation				
Operation N	Operation_1				
File name:	Operation_1				
🗹 Auto export					
Source of da	object		~		
Object:	🔲 Cube		×		

CAM material size and position \rightarrow put object into job area with position button



CAM cutter



 CAM Cutte 	r	
Cutter presets		~ + -
Tool numbe	r	1
Cutter:	V-carve	~
Cutter v-ca	rve angle	60.00000
Cutter dian	0.003 m	
Cutter flute	1	

CAM operation setup \rightarrow strategy parallel and **skin**

CAM operation setup					
Number of a	3 axis		~		
Strategy:	Parallel		~		
Distance between toolpaths 0.001 m					
Distance along toolpaths 0.0002 m					
Angle of paths			0°		
Inverse milling					
Use bridges					
Autogenerate bridges					
Skin O r			0 m		

header gcode to increase velocity spindle motor Genmitsu GS-775M 775 to 7000 (it double velocity x2)

M03 S1000 G4 P0.5 M03 S2000 G4 P0.5 M03 S3500

M03 S1000;G4 P0.5;M03 S2000;G4 P0.5;M03 S3500

Hey! Apologies for Necro'ing this thread but I think I have the exact same board and machine as you, and was running into the exact same problem. I don't know if you wound up solving your problem, but the change that worked for me was two fold:

- twist the spindle wires together between the motor and the board, adding a shield if necessary (I eventually removed the shielding when I accidentally damaged it)
- solder a 0.1uF ceramic capacitor (make sure it is bidirectional!!!) between each terminal of the spindle motor to the spindle motor body itself. Ideally, you would also solder a third capacitor

between each motor terminal, but I did not do so and have not yet had the random dropouts I did before.

From: https://wiki.csgalileo.org/ - Galileo Labs

Permanent link: https://wiki.csgalileo.org/tips/blender?rev=1744725674

Last update: 2025/04/15 16:01

