

KUU flexones 360

accelerometer

/etc/udev/hwdb.d/61-sensor-local.hwdb

```
# edit and 'systemd-hwdb update'  
sensor:modalias:acpi:KIOX010A:KIOX010A:*  
ACCEL_MOUNT_MATRIX=-1, 0, 0; 0, -1, 0; 0, 0, -1
```

run 'systemd-hwdb update'

From:
<https://wiki.csgalileo.org/> - **Galileo Labs**

Permanent link:
<https://wiki.csgalileo.org/tips/hw/kuu?rev=1668879041>

Last update: **2022/11/19 18:30**

